





Colorado Premier Garage Doors & Gate Systems

4435 W. 58th Avenue, Unit E  
 Arvada, CO 80002  
 (303) 458-5600

**Estimate**

Date	Estimate #
4/20/2017	2442

<b>Name / Address</b>
Roosevelt Ridge Association Black Hawk, CO 80422 (303) 447-8733 - Burt

<b>Ship To</b>

Description	Qty	Rate	Total
<p>Scope of work: Quote gate repairs</p> <p>After a full inspection of the property and complete gate system, we have come to the conclusion that the main issue with the gate system is that the operating loop in the ground has been dug/pulled up, probably due to graders or plow trucks during the winter or road maintenance. This will continue to happen with the road conditions it is in. Our professional proposal is to trench in all new loops into drive and have entire gate area paved by paving company after we install new loops. This will secure loops into ground and prevent any further damage to loops. Only this will prevent trucks or graders from damaging the loops</p> <p>(1) free exit loop 6 x 10 with 100' lead            (1) shadow loop 6 x 10            (2) safety loops 6 x 10</p> <p>Option:</p> <p>*Convert pre-existing receiver system for remotes to a receiver that is stable up to 450 remotes (existing receiver is only stable to 14 remotes            *New receiver system will work with existing remotes            *Star 450 315 mhz complete installed = \$450.00 X _____</p> <p>Additional remotes = \$42.00 each X _____ Quantity _____</p> <p>Any options for remote video viewing will have to be consulted with an A/V company as we are not a company that handles audio and video.</p> <p>Submitted by TJ Limmer; 4/20/17            (720) 917-9093            Price quoted reflects cash or check payment            Please add 5% for credit card payment</p> <p>X _____            Acceptance of proposal Date</p>	1	6,000.00	6,000.00

**Total** \$6,000.00

<b>Phone #</b>
303.458.5600

<b>E-mail</b>
dlenterprise@hotmail.com

<b>Web Site</b>
www.coloradopremiergaragedoors.com